



JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Power Hand Tools

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Carpenters

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, gloves (I.R.)

WESTERN HAZARD CATEGORY*

Energy Hazards

HAZARD TYPE*

Electricity

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

November 21, 2018

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Inspect power tool completely before plugging into power source	Changing blades & bits	Wear PPE
If changing bits or blades, make sure you unplug power tool		
Survey area that you are cutting or drilling into		
Make sure power source (outlet or extension cord) is properly grounded and in safe surroundings		
When power tool no longer needed, unplug and move out of work area		
When changing blades or bits, test power tool to insure proper installation		
I.R. = if required		