


JOB HAZARD ANALYSIS - Task Specific



NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Pull Pneumatic Lines in Conduit

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Controls Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, safety footwear, gloves

WESTERN HAZARD CATEGORY*

Ergonomic/Worksite Hazard

HAZARD TYPE*

Awkward posture, Strain, Working at Heights

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Doug Johnson

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Feed fish into conduit	Ladder, position	Ladder safety
Attach pneumatic line to fish tape	Ladder, position, strain	Ladder safety, use wire lubricant
Pull pneumatic line into conduit		
Remove wire from fish tape		
Rewind fish tape		