

	NEW	× REVISED
WORKPLACE TASK TO BE ANALYSED Hardwood Floor Screening/Stripping	WESTERN HAZARD CATEGORY*	DATE: March 17, 2021
DEPARTMENT Facilities Management	HAZARD TYPE*	WRITTEN BY: Zorina Stepancev
WESTERN JOB CLASSIFICATION* Caretaker	LOSS POTENTIAL RATING*	REVIEWED BY: Building Managers
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Specific Job Report	MGMT APPROVAL: M. Emerick C. Bumbacco
SEQUENCE OF TASK Assess and prepare equipment and materials	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Follow procedure for screening hardwood floors	Overexertion, strain, injuries	a) A Manager or Lead Hand should be organizing the team when screening the big area, such as gymnasium or cafeteria. Staff members should be re-instructed if required.
If needed, contact manager to ensure cooling system is running until job is completed	Heat stress, heat	